
15.83
Digital Panel Meter
IN -
IN +
Power -
Power +
Switch Positions:
dB Amplitude
Phase
Reference Power
Decimal Point
DP2
DP1
SW1D
SW1C
SW1B
SW1A
+MP5V
-MP5V
+5V
Gnd
RETURN
dB Amplitude
Peak Hold
Phase
Yellow
Green
REF Power
Antenna Ratiometer Board
+12V INPUT
Gnd
TEST
REFERENCE
PEAK
CLEAR
TONE
+12v
Yellow
Green
OFFSET
Bargraph
IN
+12V
TEST
REFERENCE
Antenna Ratiometer
Wiring Diagram
W1GHZ
Rev 1.0
2/28/2005
Figure 5